

QUALITY CONTROL OF SERA, BY USING DIFFERENT CHARTS

V. Vasu^{1*}, B. Kumara Swamy Achari² and L. Srinivasulu Reddy³

^{1,2,3}Department of Mathematics, Sri Venkateswara University, Tirupati – 517502, A.P., India

(Received on: 07-02-13; Revised & Accepted on: 02-03-13)

ABSTRACT

Quality control of sera by using \bar{X} chart, C – Chart, R – Charts for testing of sample.

Keywords: Sera, Mean Chart, Defective Chart, Range Chart.

INTRODUCTION

I. \bar{X} CHART

The \bar{X} chart is used to show the quality averages of the samples drawn from a given process. The following values must first be computed before an \bar{X} chart is constructed:

1. Obtain the mean of each sample, i.e., $\bar{X}_1, \bar{X}_2, \bar{X}_3$ etc. This is done by dividing the sum of the values included in a sample $(\sum X)$ by the number of items in the sample (n or sample size).

$$\bar{x} = \frac{\sum \bar{X}}{n}$$

2. Obtain the mean of the sample means, i.e., $\bar{\bar{X}}$ This is done by the sum of the sample means $(\sum \bar{X})$ by the number of samples to be included in the chart.

$$\bar{\bar{X}} = \frac{\sum \bar{X}}{\text{Number of samples}}$$

3. The control limits are set at

$$\text{U.C.L.} = \bar{\bar{X}} + 3\sigma \bar{X}$$

$$\text{L.C.L.} = \bar{\bar{X}} - 3\sigma \bar{X}$$

$$\text{where } \sigma_x = \frac{\sigma}{\sqrt{n}} \text{ and } \sigma = d' \bar{R}$$

\bar{R} is a biased estimator of σ and d' is the correction factor. Therefore the control limits are.

$$\text{U.C.L.} = \bar{\bar{X}} + A_2 \bar{R}$$

$$\text{L.C.L.} = \bar{\bar{X}} - A_2 \bar{R}$$

II. C – CHART

The C – Chart is designed to control the number of defects per unit. It is very popularly used in statistical work. The central line of the control chart for C is \bar{C} and the 3- sigma control limits are:

$$\text{U.C.L.} = \bar{C} + 3\sqrt{\bar{C}}$$

$$\text{L.C.L.} = \bar{C} - 3\sqrt{\bar{C}}$$

Corresponding author: V.Vasu^{1*}

Department of Mathematics, Sri Venkateswara University, Tirupati – 517502, A.P., India

III. R –CHART

The R – chart is used to show the variability or dispersion of the quantity produced by a given process. R chart (or σ chart) is the companion chart to \bar{X} chart and both are usually required for adequate analysis of the production process under study. The R chart is generally presented along with the \bar{X} chart. The general procedure for constructing the R chart is similar to that for the \bar{X} chart. The required values for constructing the R chart are:

1. The range of each sample. R
2. The mean of the sample ranges. \bar{R}
3. U.C.L. and L.C.L.

$$\text{U.C.L.}_R = \bar{R} + 3\sigma_R; \text{ and}$$

$$\text{L.C.L.}_R = \bar{R} - 3\sigma_R$$

where σ_R = the standard error of the range

Chart – 1 (\bar{X} - Chart)

1. **Specimen analyzed:** Quality control serum
2. **Determination:** Glucose by glucose oxidase method
3. **Mean glucose value:** 100 mg/dl.

Table: 1

Date	Sample –I Individual test values	Date	Sample –II Individual test values	Date	Sample - III Individual test values	Sample mean \bar{X}	Sample Range R
12.2.12	95	18.2.12	98	23.2.12	96	96.3	3
13.2.12	98	19.2.12	101	24.2.12	100	99.6	3
14.2.12	100	20.2.12	104	25.2.12	102	102	4
15.2.12	97	21.2.12	97	26.2.12	98	97.3	1
16.2.12	106	21.2.12	106	26.2.12	108	106.6	2
17.2.12	110	22.2.12	100	27.2.12	105	105	10

$$\bar{X} = \frac{\Sigma \bar{X}}{n}$$

$$\bar{\bar{X}} = \frac{\Sigma \bar{X}}{\text{Number of samples}}$$

- iii. The control limits are set at

$$\text{U.C.L.} = \bar{\bar{X}} + 3\sigma_{\bar{X}}$$

$$\text{L.C.L.} = \bar{\bar{X}} - 3\sigma_{\bar{X}}$$

where

$$\sigma_x = \frac{\sigma}{\sqrt{n}} \text{ and } \sigma = d' \bar{R}$$

\bar{R} is abased estimator of σ and d' is the correction factor. The values of d' are tabulated and are tabulated and are given in the appendix at the end of the book.

$$\text{U.C.L.} = \bar{\bar{X}} + A_2 \bar{R}$$

$$\text{L.CL} = \bar{\bar{X}} - A_2 \bar{R}$$

1. The mean of each sample \bar{X} is given in the table for example \bar{X} for the first sample is $\frac{289}{3} = 96.33$

$$\bar{\bar{X}} = \frac{\sum \bar{X}}{6} = \frac{606.8}{6} = 101.13$$

2. The mean of the sample means $\bar{\bar{X}}$ is obtained that

3. The value of \bar{R} is computed from the values of R shown in the table 1. The sample value of R for the first sample is computed as follows.

$$R = 98 - 95 = 3$$

4. The value or \bar{R} , i.e. the mean of the values of R is obtained as follows:

$$\bar{R} = \frac{\sum R}{6} = \frac{23}{6} = 3.83$$


$$5. \text{U.C.L} = \bar{\bar{X}} + A_2 \bar{R}$$

[The table value of A_2 for n=6 is 0.483]

$$\begin{aligned} \therefore U.C.L &= \bar{\bar{X}} + A_2 \bar{R} \\ &= 101.13 + 0.483 \times 3.83 \\ &= 101.13 + 1.849 \\ &= 102.97 \text{ mg/dl app} \end{aligned}$$

$$\begin{aligned} L.C.L &= \bar{\bar{X}} - A_2 \bar{R} \\ &= 101.13 - 0.483 \times 3.83 \\ &= 101.13 - 1.849 \\ &= 99.281 \text{ mg/dl app} \end{aligned}$$

Drawing a chart:



All the points except to points are not falling with in the control Limits. The process is not in a state of control

R –chart

The required values for the R chart are:

1. The range of each sample, R
2. The mean of the sample ranges R

$$\bar{R} = \frac{\sum R}{6} = \frac{23}{6} = 3.83$$

$$U.C.L.R = D_4 \bar{R}$$


$$L.C.L.R = D_3 \bar{R}$$

From the table for the sample of size 6, we find that

$$D_3 = 0, D_4 = 2.004$$

$$\therefore U.C.L = D_4 \bar{R} = 2.004 \times 3.83 \\ = 7.67$$

$$L.C.L = D_3 \bar{R} = 0 \times 3.83 \\ = 0$$



CONCLUSION

The fact that in the graph all sample points are falling except one point with in 3σ control limits can be interpreted as implying that the process is in a state of statistical control.

CHART – 2 (C – Chart)

The following table gives the number of errors of alignment observed at final inspection of a In order to check the accuracy of the analysis run and also the quantity control sera, detect systematic errors, when a systematic error (all low values or all high values) is present the cusum values will steadily increase.

Table - 2

Date	Mean Value	Individual test values	Defectives
12.2.12	100	98	+2
13.2.12	100	101	-1
14.2.12	100	96	+4
15.2.12	100	97	+3
16.2.12	100	106	-6
17.2.12	100	106	-6
18.2.12	100	96	4
19.2.12	100	102	-2
20.2.12	100	100	0

21.2.12	100	97	3
22.2.12	100	98	2
23.2.12	100	95	+5
24.2.12	100	103	-3
25.2.12	100	97	3

$$U.C.L. = \bar{C} + 3\sqrt{\bar{C}}$$

$$L.C.L. = \bar{C} - 3\sqrt{\bar{C}}$$

\bar{C} CHART:


The computation required for preparing this chart

(i) \bar{C} , i.e average number of defects

$$\bar{C} = \frac{8}{14} = 0.57$$

$$\begin{aligned} U.C.L. &= \bar{C} + 3\sqrt{\bar{C}} \\ &= 0.57 + 3 \times 0.75 \\ &= 0.57 + 2.26 \\ &= 2.83 \end{aligned}$$

$$\begin{aligned} L.C.L. &= \bar{C} - 3\sqrt{\bar{C}} \\ &= 0.57 - 3 \times 0.75 \\ &= 0.57 - 2.26 \\ &= -1.69 \text{ or } 0 \text{ (zero) since L.C.L cannot be negative.} \end{aligned}$$



CONCLUSION

It is clear from the chart that most of the point of this sample falls outside the control limits and this is to be treated as a danger signal.

REFERENCES

1. S.P. Gupta "Statistical Methods" Sultan Chand & Sons, Education Publishers, New Delhi, 37th edition.
2. Grant, E.L. "Statistical Quality Control". New York. McGraw – Hill, 1989.
3. Juran, J.M. "Quality Control Handbook". New York, Mc Graw – Hill, 1989.
4. Ishikawa, K. "Guide to quality control". White plains. N. Y. Asian Productivity Organization, 1984.

Source of support: Nil, Conflict of interest: None Declared